



06/2015

Flex Series Dev Kit Quick Start

Getting started is quick and easy...

Development Kit contains

- USB Flash Drive
 - Flexware App
 - Instructions for Use
- AC Wall Adaptor Power Supply
- Interface Cable to Connect Sensor to PC

For use with Flex Series Sensors

- H4360
- H6

Installation

1. Plug the USB flash drive into the USB port on the PC computer.
2. Double-click *Rieker Flexware™ Toolkit* and follow the instructions to install the software.
3. See Instructions for Use Guide located on USB flash drive for details.

NOTE: Due to varying security settings on every computer, an error message may occur during install. This is normal and the installation can be safely continued.

The information and material presented may not be published, broadcast, rewritten, or redistributed without the expressed written consent of Rieker® Inc. The content presented is provided for informational purposes only and subject to change.
©2015 Rieker® All Rights Reserved.